Test Report
Quality of Bitumen

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Test Method	IS : 73 – 1992 & Specification for Road & Bridge Works, MORT&H,
Grade of Bitumen	60 / 70
Location	Hot Mix Plant
Material	Bitumen
Sample No	1
Date	16-May-2018

Sl. No.	Description	Test Results	Requirement as per IS:73 - 1992
1	Penetration at 25^0C , 1 / 10 mm	66	60 - 70
2	Softening Point, (^{0}C)	50	45 – 55
3	Specific Gravity	1.1	Min. 0.97
4	Ductility at 27^0C, in cm	81	Min. 75
5	Flash Point, (^{0}C)	181	Min. 175

Note:

i. The results indicated above are based on the tests carried out on the sample at site.
ii. The results relate only to the items tested.
iii. This test report should not be reproduced except in full, without written approval of this laboratory.
iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore

Test Report
Quality of Bitumen

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Test Method	IS : 73 – 1992 & Specification for Road & Bridge Works, MORT&H,
Grade of Bitumen	60 / 70
Location	Hot Mix Plant
Material	Bitumen
Sample No	2
Date	19-May-2018

Sl. No.	Description	Test Results	Requirement as per IS:73 - 1992
1	Penetration at 25^{0}C , 1 / 10 mm	63	60 – 70
2	Softening Point, (^{0}C)	52	45 – 55
3	Specific Gravity	1.1	Min. 0.97
4	Ductility at 27^{0}C, in cm	80	Min. 75
5	Flash Point, (^{0}C)	181	Min. 175

Note:

i. The results indicated above are based on the tests carried out on the sample at site.
ii. The results relate only to the items tested.
iii. This test report should not be reproduced except in full, without written approval of this laboratory.
iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	1
Date	21-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.657	1.659	1.653
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.016	0.018	0.012
6	Rate of spread (d/a)	kg / m^2	0.400	0.450	0.300
7	Average	kg / m^2	0.383		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.383 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	2
Date	21-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.656	1.658	1.652
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.015	0.017	0.011
6	Rate of spread (d/a)	kg / m^2	0.375	0.425	0.275
7	Average	kg / m^2	0.358		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.358 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	3
Date	21-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.656	1.659	1.653
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.015	0.018	0.012
6	Rate of spread (d/a)	kg / m^2	0.375	0.45	0.3
7	Average	kg / m^2	0.392		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.392 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Test Report

Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	4
Date	24-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.657	1.659	1.651
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.016	0.018	0.01
6	Rate of spread (d/a)	kg / m^2	0.400	0.450	0.250
7	Average	kg / m^2	0.367		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.367 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	5
Date	24-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.655	1.661	1.655
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.014	0.02	0.014
6	Rate of spread (d/a)	kg / m^2	0.350	0.500	0.350
7	Average	kg / m^2	0.400		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.400 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	6
Date	24-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.658	1.66	1.65
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.017	0.019	0.009
6	Rate of spread (d/a)	kg / m^2	0.425	0.475	0.225
7	Average	kg / m^2	0.375		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.375 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	7
Date	25-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.656	1.662	1.654
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.015	0.021	0.013
6	Rate of spread (d/a)	kg / m^2	0.375	0.525	0.325
7	Average	kg / m^2	0.408		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.408 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore

Test Report
Rate of Spread of Tack Coat

Project Name	1. Improvement of roads and drain at kogilu layout main road and cross road in ward no 05 byatarayanapura sub division 2. Improvement of roads and drain at kattigenahalli kuvempunagara cross road in ward no 05 byatarayanapura sub division 3. Improvement of drain at dwarakanagara srirama temple road in ward no 05 byatarayanapura sub division 4. Improvement of roads and drain at kattigenahalli surrounding area in ward no 05 byatarayanapura sub division 5. Improvement of roads and drain at nirantara layout in ward no 05 byatarayanapura sub division 6. Improvement of drain and asphalting to road at agrahara layout harihara temple surrounding area in ward no 05 byatarayanapura sub division
Client	Executive Engineer Project Division Yelahanka Zone
Job No	MCTPL/BBMP/Project Division Yelahanka Zone /PMC/2017-2018/QR/P-8/02
Mix Type	Bituminous Concrete (BC)
Contractor	Sri A Chennareddy
Location	At Site
Material	Bitumen
Sample No	8
Date	25-May-2018

Sl. No.	Determination	Unit	Test No 1 Longitudinal Distribution		
1	Size of Plate (mxn)	m^2	0.2x0.2	0.2x0.2	0.2x0.2
2	Area of the Plate (a)	m^2	0.04	0.04	0.04
3	Initial weight of the empty Plate (b)	kg	1.641	1.641	1.641
4	Final weight of plate after application of Tack Coat (c)	kg	1.657	1.661	1.651
5	Weight of Prime coat/ Tack Coat (d = c-b)	kg	0.016	0.02	0.01
6	Rate of spread (d/a)	kg / m^2	0.400	0.500	0.250
7	Average	kg / m^2	0.383		
8	Specified Limit	kg / m^2	Not less than 0.25 kg / m^2		

Results: Rate of Spread of Prime Coat / Tack Coat is: 0.383 kg / m2

Note:

i. The results indicated above are based on the tests carried out on the sample at site.

ii. The results relate only to the items tested.

iii. This test report should not be reproduced except in full, without written approval of this laboratory.

iv. Any query regarding the report must be reported immediately.

For Mecadez Core Technologies Private Limited

Authorised Signature

Asst. Executive Engineer
Project Division
Yelahanka Zone
Bangalore